


# Analog Meters

## Classification of Analog Meters



## Torque in Analog Meter

### 1. Deflecting Torque ( $T_D$ )

Deflecting torque is proportional to quantity under measurement. This torque deflect the pointer away from initial or zero position.

$$T_D \propto \text{Measurable quantity}$$

### 2. Controlling Torque ( $T_C$ )

The controlling torque is opposite to deflecting torque. When, deflecting torque equals to controlling torque, pointer comes to final steady state position.

At equilibrium,

$$T_C = T_D$$

**Note:**

- Control torque is also used to bring the pointer in zero initial position, if there is no deflecting torque.
- Except in PMMC, in all other instruments if the control spring is failed or broken then pointer moves to the maximum position of scale.
- Control torque is provided by
  - Spring control
  - Gravity control

**3. Damping Torque**

It is used to damp out oscillation at final steady state position. The time response of the instrument depends on damping torque.

Damping torque provided by:

- Air friction damping:** Used where low magnetic fields are produced
- Fluid friction damping:** Used where deflecting torque is minimum.
- Eddy current damping:** Used where permanent magnet produces the required deflecting torque.

**Error in Analog Meters****1. Frictional Error**


To reduce the frictional error, the torque to weight ratio of the instrument should be high.

**2. Temperature Error**

Due to change in temperature, change in resistance of meters and shunts and series multiplier occurs. To reduce this effect, resistances are made up of manganin material.

**3. Frequency Error**

Due to change in frequency, error produce in instrument because change in frequency cause change in reactance. To reduce this error, a capacitance is used in case of voltmeter and for ammeter, the time constant and shunt impedances are maintained at same value.

**permanent Magnet Moving Coil (PMMC)****□ Deflection torque**

$$T_D = nBAI$$

$$T_D = GI$$

where,  $G = nBA$   
 $n$  = Number of turns  
 $B$  = Flux density  
 $A$  = Area of core  
 $I$  = Current to be measured

**□ Final steady state deflection**

$$\theta = \left( \frac{G}{K} \right) I$$

where,  $K$  = Spring constant


**Note:**

- PMMC instrument measures only DC or average values.
- Scale is linear.
- Spring is used for controlling torque.
- Damping torque provided by eddy current damping.
- It has more, torque to weight ratio so accuracy and sensitivity is higher compare to other instrument.

- In direct measurement, the PMMC measures upto a current of 50 mA or a voltage of 100 mV, without any external device.

## Enhancement of Ammeters and Voltmeters

### 1. Ammeter Shunts



$$I_{sh} R_{sh} = I_m R_m$$

$$I = \left(1 + \frac{R_m}{R_{sh}}\right) I_m$$

where,  $I$  = Current to be measured ;

$I_m = I_{fs}$  = Full scale deflection current ; A

$R_m$  = Internal resistance of meter ;  $\Omega$

$R_{sh}$  = Resistance of the shunt ;  $\Omega$

□ Shunt resistance

$$R_{sh} = \frac{R_m}{m - 1}$$


where,  $m = \frac{I}{I_m} = 1 + \frac{R_m}{R_{sh}}$

$m$  = Multiplying factor for shunt

**Note:**

To reduce the temperature effect, swamp resistance made up of manganin is added in series with ammeter.

### 2. Universal or Ayrton Shunt



(Multi-range ammeter using universal shunt)

□ For switch at a position 1

$$R_1 = \frac{R_m}{(m - 1)}$$

□ For switch at a position 2


$$R_2 = \frac{(R_1 + R_m)}{m_2}$$

□ For switch at a position 3

$$R_3 = \frac{(R_2 + R_m)}{m_3}$$

where,  $m_1 = \frac{I_1}{I_m}$ ,  $m_2 = \frac{I_2}{I_m}$ ,  $m_3 = \frac{I_3}{I_m}$

### 3. Voltmeter Multipliers



□ Multiplying factor for multiplier


$$m = \frac{V}{v} = 1 + \frac{R_s}{R_m}$$

- Resistance of multiplier

$$R_s = (m - 1)R_m$$

where,  $R_s$  = Multiplier resistance  
 $R_m$  = Internal resistance of meter

#### 4. Potential Divider Arrangement



$$R_1 = (m_1 - 1) R_m$$

$$R_2 = (m_2 - m_1) R_m$$

$$R_3 = (m_3 - m_2) R_m$$

$$R_4 = (m_4 - m_3) R_m$$

where,  $R_1$  = Resistance between point a and b

$R_2$  = Resistance between point b and c

$R_3$  = Resistance between point c and d

$R_4$  = Resistance between point d and e

❑ **Voltmeter Sensitivity ( $S_v$ )**

$$S_V = \frac{1}{I_{IS}} = \frac{R_s + R_m}{V} \Omega/V$$

**Remember:**

To reduce loading effect, a voltmeter with higher value of sensitivity is preferred.

## Moving Iron Instruments

▣ Deflecting torque

$$T_d = \frac{1}{2} l^2 \frac{dL}{d\theta}$$

- ▣ Deflection

$$\theta = \frac{1}{2} \frac{I^2}{K} \frac{dL}{d\theta}$$

- For linear scale


$$\theta \cdot \frac{dL}{d\theta} = \text{constant}$$

Scale is cramped at lower and higher end.

**Note:**


- Moving iron instrument measure both A.C. and D.C. quantities.
- In case of A.C., it measure RMS value.
- Scale is non linear.
- Controlling torque is provided by spring and air friction damping is used.
- Curve between  $\frac{dL}{d\theta}$  and  $\theta$  is rectangular hyperbola.

### Shunts for Moving Iron Instruments



$$\frac{I_{sh}}{I_m} = \frac{R}{R_{sh}} \sqrt{1 + (\omega L_{sh} / R_{sh})^2}$$


## Multipliers for Moving Iron Instruments



□ Voltage multiplying factor

$$m = \frac{V}{v} = \frac{\sqrt{(R + R_s)^2 + \omega^2 L^2}}{\sqrt{R^2 + \omega^2 L^2}}$$

## Errors in Moving Iron Instruments



□ Shunt capacitance

$$C = 0.41 \frac{L}{R_s^2}$$

□ Eddy currents

When  $\omega$  is small

$$r_e = \frac{\omega^2 M L_e L}{R_e^2}$$

When  $\omega$  is large


$$r_e = \frac{M L}{L_e} = \text{constant}$$

where,  $R_e, L_e$  = resistance and inductance of eddy current path

Note:

- Moving iron instrument is not suitable for measurement of current or voltage for frequency above 125 Hz because eddy current is constant at higher frequency.
- If meter time constant is equal to shunt time constant then ammeter is made independent of input supply frequency.
- The voltmeter is made independent of input supply frequency by connecting a capacitor in parallel to the series multiplier resistance  $R_s$ .
- To reduce hysteresis error, the iron part of moving iron is made up of Nickel iron alloy.
- To reduce the external stray magnetic field, the instrument is kept inside the iron case or iron shielding is done.

## Electrodynamometer



(a) If  $i_1$  and  $i_2$  are D.C. current i.e.  $i_1 = i_2 = I$

$$T_d = I^2 \frac{dM}{d\theta}$$

(Measure average value)

(b) If  $i_1$  and  $i_2$  are A.C. current and no phase shift

$$i_1 = i_2 = I$$

$$T_d = I^2 \frac{dM}{d\theta}$$

(Measure RMS value)

(c) If  $i_1 = I_{m1} \sin \omega t$  and  $i_2 = I_{m2} \sin(\omega t - \phi)$

$$T_d = I_1 I_2 \cos \phi \frac{dM}{d\theta}$$


(Measure RMS value)

Where,  $I_1 = \frac{I_{m1}}{\sqrt{2}}$  and  $I_2 = \frac{I_{m2}}{\sqrt{2}}$

**Note:**

- Electrodynamometer instrument is a transfer instrument.
- It measures both A.C. and D.C.
- Scale is nonlinear.
- Its sensitivity is lesser than PMMC and M.I. type instruments.

**Ratiometer**



- Deflecting torque acting on coil 1

$$T_{d1} = N_1 B l_1 d_1 I_1 \cos \theta$$

- Deflecting torque acting on coil 2

$$T_{d2} = N_2 B l_2 d_2 I_2 \cos \theta$$

where,  $I_1, I_2$  = current in coil 1 and 2

$N_1, N_2$  = number of turns in coil 1 and 2

$l_1, l_2$  = length of coil 1 and 2

$d_1, d_2$  = width of coil 1 and 2

$B$  = flux density of magnetic field

- Deflection at equilibrium

$$\theta = k \left( \frac{I_1}{I_2} \right)$$