



ERROR



Difference between the result of the measurement and the true value of what you were measuring

Types of Error



RANDOM ERROR

Random errors appear randomly because of the operator, fluctuations in the external conditions and variability of the measuring instruments. The effect of random error can be somewhat reduced by taking the average of measured values. **Random errors** have no fixed sign or size.

Thus they are represented in the form $A \pm \alpha$

SYSTEMATIC ERROR

Systematic error occurs due to an error in the **procedure or miscalibration** of the instrument etc. Such errors have same **size and sign** for all measurements. Such errors can be determined.

The systematic error is removed **before beginning calculations**. **Bench error** and **zero error** are examples of **systematic error**.

ABSOLUTE ERROR

Error may be expressed as absolute measures, giving the size of the error in a quantity in the same units as the quantity itself.

Least Count Error :- If the instrument has known least count, the absolute error is taken to be **half** of the least count unless otherwise stated.

RELATIVE (OR FRACTIONAL) ERROR

Error may be expressed as relative measures, giving the ratio of the quantity's error to the quantity itself

$$\text{Relative Error} = \frac{\text{Absolute error in a measurement}}{\text{Size of the measurement}}$$



RULES OF ERROR MEASUREMENT

ADDITION & SUBTRACTION RULE

01

The absolute random errors **add**

If $R = A + B$, or $R = A - B$, then $r = a + b$



RULES

PRODUCT & QUOTIENT RULE

02

The relative random errors **add**

If $R = AB$, or $R = \frac{A}{B}$, then $\frac{r}{R} = \frac{a}{A} + \frac{b}{B}$

POWER RULE

03

When a quantity Q is raised to a power P , the relative error in the result is P times the relative error in Q . This also holds for negative powers.

$$\text{If } R = Q^P, \text{ then } \frac{r}{R} = P \times \frac{q}{Q}$$


VERNIER CALLIPERS

Least count of Vernier Callipers

The least count of Vernier Callipers (**v.c**) is the minimum value of correct estimation of length without eye estimation. If N^{th} division of **vernier calliper coincides** with **($N-1$)** division of main scale, then

$$N(vs) = (N-1) ms \Rightarrow 1 vs = \frac{N-1}{N} ms$$

vs = Vernier Scale Reading : ms = Main Scale Reading




Vernier Constant = $1 ms - 1 vs = \left(1 - \frac{N-1}{N}\right) ms = \frac{1}{N} ms$, which is equal to the value of the smallest division on the main scale divided by total number of divisions on the vernier scale.

SCREW GAUGE (OR MICROMETER SCREW)

The instrument is provided with **two scales**

- The main scale or pitch scale is (M) graduated along the axis of screw.
- The cap-scale or head scale (H) around the edge of the screw head.



Pitch :- The pitch of the instrument is distance between two consecutive threads of the screw which is equal to the distance moved by the screw due to one complete rotation of the cap. Thus for,

10 rotation of cap = 5 mm, then pitch = 0.5 mm.

Least count :- The minimum (or least) measurement (or count) of length is equal to one division on the head scale which is equal to pitch divided by the total cap divisions.

$$\text{Least count} = \frac{\text{Pitch}}{\text{Total cap divisions}}$$

Measurement of length by screw gauge

Length, $L = n \times \text{pitch} + f \times \text{least count}$,

where **n = main scale reading & f = caps scale reading**

Zero Error

In a perfect instrument the zero of the main scale coincides with the line of gradation along the screw axis with no zero-error, otherwise the instrument is said to have zero-error which is equal to the cap reading with the gap closed. This error is positive when zero line of reference line of the cap lies **below** the line of gradation and vice-versa. The corresponding corrections will be just opposite.

